


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-224	Smoke	8/10/2009	ADS/TM	S19KK_012MH	Dry	Yes	348.84



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-224	Smoke	8/10/2009	ADS/TM	S19KK_012MH	Dry	Yes	348.84

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19KK_061G1	S19KK_061DE	S19KK_012MH	87.2326	8
S19MM_032G1	S19MM_032UN	S19KK_012MH	115.699	8
S19KK_012G1	S19KK_012MH	S19MM_009MH	145.909	6

Observations & Photos

Obs_ID S1028-224-OB01

Address 2111 Smallwood St


Status Private

Source Cleanout

Location Yard - back

Nearest MH S19KK_012MH

Comments Smoke from cleanout in back yard. 2111 Smallwood St.



Picture \S1028-224-OB01-P01.jpg

Comments Back of house, 2111 Smallwood St.